


PlasticsJoining * Consulting

Supportive Consulting -
From the Idea
to the Final Product

Project flow - Not only in the field of plastics joining



A project normally has four phases:

It starts with the conceptualisation, then goes into the definition and development phases, to conclude with the production phase.

The cost requirements diagram illustrates that the influence of the concept, definition and development phases on the required costs can be very high. However, the costs actually required during these phases are still relatively low.

This means that important technical and economic benchmarks for the entire project are already set during these phases.

Conclusion:

- Inventive concept phase
 - Thoroughly researched definition phase
 - Optimally implemented development phase
- reduce the total costs


We provide you with the support you need:

PlasticsJoining *
Consulting

Walter Strohfuss
Manager Plastics Joining Consulting
Tel.: 06074/497-170
Fax: 06074/497-599
Email: walter.strohfuss@bransoneurope.com

Project Flow in Detail or Increasing Competitiveness of Customers

The way:



The target:

With PlasticsJoining Consulting as partner,
you achieve an optimum cost/benefit ratio